

INSTRUCTION SHEET

ELECTRONIC INDICATOR WITH FRACTIONS



FEATURES


1. ON/OFF
2. Floating ZERO
3. Absolute/Incremental readings
4. Direct mm/in/fraction conversion
5. Hold
6. Battery Cover
7. Lug back and 3/8 stem diameter
8. Top lifting knob
9. 4-48 contact point
(reversible with top lifting knob)



OPERATION

1. Turn the indicator on or off press ON/OFF (1) momentarily.
2. To ZERO the indicator at any location press ZERO (2).
 - a. This can be used in either ABS or INC.
3. Press mm/in/F (4) to display readings in either inch, metric, or fraction.
4. Press ABS/INC (3) to toggle between Absolute and Incremental reading. ZERO may be set at any location in either mode.

Specifications	
Measuring Range	0-1" / 025mm
Reading	0.0005" / 0.01mm / 1/128th
Accuracy	0.001" / 0.03mm
• Repeatability	0.0005" / 0.01mm
• Display	LCD (11.0 mm high)
• Maximum Measuring Speed	1.5m per second
• Battery	3V typeCR2032 Lithium
• Battery Life	Approx 1 year



MAINTENANCE

- Avoid contact with liquids and excessive humidity.
- If the instrument requires cleaning, use only isopropyl alcohol and a soft touch cloth.
- Battery is low when the display flashes. To replace the battery, use a small screwdriver to open the side battery compartment (6). Uses 1 CR2032 battery.

REV.10-24

⚠ WARNING: This product can expose you chemicals including lead, which is/are known to the state of California to cause cancer, birth defects or other reproductive harm. For more information, go to: www.P65Warnings.ca.gov

